## Glenda Edwards Goh

From: reac\_trdba1@hud.gov

Sent:Friday, December 02, 2016 12:05 PMTo:Glenda Edwards Goh; David Bustamante

 Cc:
 Catherine.D.Lamberg@hud.gov; reac\_trdba1@hud.gov

 Subject:
 Response to your Appeal, inspection number 581644

Please do not reply to this email. REAC does not accept replies to notification emails. Please for all comments posted on our website.



U.S. Department of Housing and Urban Development

550 12th Street, SW Suite 100 Washington, DC 20410

OFFICE OF PUBLIC AND INDIAN HOUSING REAL ESTATE ASSESSMENT CENTER

December 2, 2016

Ms. Glenda Edwards-Goh Executive Director 2624 Salem Turnpike, NW Roanoke, VA 24017

RE: Inspection Number: 581644

Property Name: Morningside Manor

Property ID: VA011000208

Inspection Release Date: October 11, 2016 Original Physical Inspection Score: 67.45 New Physical Inspection Score: 71.05

Dear Ms. Glenda Edwards-Goh:

Thank you for your November 9, 2016 letter requesting a review of the above referenced inspection letter on November 17, 2016. We have completed our review in accordance with applicable regularity.

Based on the documents you provided with your letter, below is our determination:

Location : Site - MORNINGSIDE MANOR Deficiency : HS - Sharp Edges (Hazards) Documentation: Management's statement that trash service was delayed by one day and did not company the day of inspection. The property only has one maintenance man and rather than assisting the trash collection of the day due to operational issues on their part.

Comments: Documents related to the deficiency were not received in the REAC prior to the statu deficiency was not evaluated. Please note, this request is considered a Technical Review. Database "Adverse Conditions Beyond Owner Control" are to be caused by circumstances beyond the PHA as damage from a natural disaster or a third party private or public entity working near a property. beyond dumpster, trash company would no have picked up

Status: Decline

Location: Building 208 - MORNINGSIDE MANOR HIGHRISE - Building Exterior

Deficiency: BE- Missing/Damaged Caulking/Mortar (Walls)

Documentation: A copy of the contract dated 9/27/16, with Russell's Remodeling, LLC to make rebuilding exterior finishes within 75 days from date of Notice to Proceed; photo of building exterior Comments: The Notice to Proceed was not received in your submittal however, due to the inspect "Contractors on site doing tuck pointing work on building, grinding out and replacing bad mortar be restored.

Status: Accept

If a deficiency cited on the property/development that is the subject of this letter is a database adjute record it in our systems so that if a deficiency for that item is cited in a future inspection, it will be inspection report is released.

This concludes REAC's review of your technical review/database adjustment request and the phys shown above is (are) the final score(s).

Should you have any questions concerning this review and/or suggestion(s) to make this process recontact us at <a href="REAC\_TRDBA@hud.gov">REAC\_TRDBA@hud.gov</a>. We remind you that information on submitting technical adjustments, including pre-database adjustments, as well as HUD's regulations, is at:

http://portal.hud.gov/hudportal/HUD?src=/program\_offices/public\_indian\_housing/reac/products/

Sincerely,
Samuel Tuffour
Program Manager
Physical Assessment Sub-system

Tracking Number: Appeal number 1333/TAC-573019/J.L.

for all comments posted on our website.	