

Glenda Edwards Goh

From: reac_trdba1@hud.gov
Sent: Tuesday, December 06, 2016 9:50 AM
To: Glenda Edwards Goh; David Bustamante
Cc: Catherine.D.Lamberg@hud.gov; reac_trdba1@hud.gov
Subject: Response to your Appeal, inspection number 581634

Please do not reply to this email. REAC does not accept replies to notification emails. Please follow for all comments posted on our website.



U.S. Department of Housing and Urban Development
550 12th Street, SW
Suite 100
Washington, DC 20410

OFFICE OF PUBLIC AND INDIAN HOUSING
REAL ESTATE ASSESSMENT CENTER

December 6, 2016

Ms. Glenda Edwards Goh
Executive Director
2624 Salem Turnpike, NW
Roanoke, VA 24017

RE: Inspection Number: 581634
Property Name: Jamestown Place
Property ID: VA011000207
Inspection Release Date: October 12, 2016
Original Physical Inspection Score: 78.54
New Physical Inspection Score: 86.04

Dear Ms. Glenda Edwards Goh:

Thank you for your November 16, 2016 letter requesting a review of the above referenced inspection. We received your letter on November 22, 2016. We have completed our review in accordance with applicable regulations.

Based on the documents you provided with your letter, below is our determination:

Location : Site - JAMESTOWN PLACE
Deficiency : Site - Erosion/Rutting Areas (Grounds)

Documentation : A letter from L.M.W., P.C. stating that the low elevation of the soil in relation to result of erosion, but is the result of a failure to fully backfill against the sidewalk when it was completed. Over the passing of time the settlement of the soil that was disturbed when the sidewalk was installed.

Comments : Documentation was sufficient to support request.

Status : Accept

If a deficiency cited on the property/development that is the subject of this letter is a database adjustment, please update the record in our systems so that if a deficiency for that item is cited in a future inspection, it will be noted in the inspection report is released.

This concludes REAC's review of your technical review/database adjustment request and the physical assessment shown above is (are) the final score(s).

Should you have any questions concerning this review and/or suggestion(s) to make this process more efficient, please contact us at REAC_TRDBA@hud.gov. We remind you that information on submitting technical adjustments, including pre-database adjustments, as well as HUD's regulations, is at:

http://portal.hud.gov/hudportal/HUD?src=/program_offices/public_indian_housing/reac/products/

Sincerely,

Samuel Tuffour

Program Manager

Physical Assessment Sub-system

Tracking Number: Appeal number 1376/TAC-573126/J.L.

Please do not reply to this email. REAC does not accept replies to notification emails. Please follow the instructions for all comments posted on our website.